

FLOOD ALLEVIATION CAPITAL PROJECTS & MAINTENANCE WORKS COMPLETED

Location	Issue/Works	No. of properties protected
1. Porchester Road - Wotton brook, Hucclecote	Surface water/flooding from brook - works to include Property Level Protection measures to be fitted to 22 properties. Jointly funded scheme – DEFRA/County and City Council	22
2. 162/164 Bristol Road, Moreland	Surface water flooding issues – works to include Property Level Protection measures to be fitted to both properties. Jointly funded scheme – County and City Council	2
3. Pearwood Way, Tuffley - Whaddon brook	Installation of trash over face of Relief culvert to prevent access and blockages.	Approximately 20
4. Milton Avenue, Podsmead	Installation of trash over face of culvert at the end of the open ditch to prevent blockages.	Approximately 10+
5. Yarrow Close, Matson & Robinswood	Surface water pouring off Robinswood Hill during heavy rain and onto residential properties. Works completed to divert flows away from properties and into an existing pond. Additional works included the increase to the size of the current pond, ground reprofiling and the digging of new drainage ditches.	2
6. St Peters School, Stroud Road – Wotton brook, Tuffley	Surface water issues in the area and large volumes of water are pouring off the site during heavy rain. Phase 1 of the scheme is now complete and included the building of 3 rain water gardens to deal with surface water from a number of the buildings on site to reduce run-off, create storage capacity, and improve water quality, in addition to habitat creation and a valuable learning resource. The scheme is a joint venture between Gloucester City Council, the Environment Agency and St Peter’s School.	6+ Highway,
7. Bourton Road	Surface water pouring from a Highways Public Open Space into the front gardens and against the threshold of a number of properties during heavy rain. The works involved the laying a new short section of drain across the footpath and the construction of a swale to intercept overland flows.	Approximately 6
8. Coney Hill – Wotton brook Tributary	Clearance of a 140 metre section of banks and channel to the rear of houses in York Road	Approximately 8

Location	Issue/Works	No. of properties protected
9. Whaddon brook – Tuffley	Clearance of banks and channel adjacent the rear of properties in Bybrook Road/Bybrook Gardens	Approximately 6+
10. Off Lobleys Drive open space, Hucclecote	Ditches to the rear of properties were overgrown and had been used to fly tip green waste and other items including furniture, garden equipment, rubble etc. Issues with an overgrown pond to the rear of Oakwood Drive and large willows which require pollarding (some tree works still outstanding). Works also included a letter drop to residents who back on to the ditches, clearance of ditches (approximately 500 metres) and pond.	Approximately 30
11. Quedgeley - Dimore Tributary	Clearance of a 400+ metre section of the Dimore tributary in Quedgeley from Saddlers Road down to Merlin Drive	Approximately 20
12. Barnwood Park, trash screen	Structural survey of retaining wall identified minor works including repointing works and removal of undergrowth which has now been completed.	
13. Bristol Road, Quedgeley surface water drainage into Dimore trib	Works to improve the conveyance of surface water via investigations and associated works including a CCTV survey, high pressure jetting and removal of silt. Works to one side of the carriageway have now been completed.	Approximately 4
15. Dimore Tributary, Quedgeley	Clearance of silt from culvert which is causing flow to back up during heavy rainfall	4
Total		Approximately 140 properties