

Appendix 2 – Site issues

Flooded access road – Dec 2022



Flooding Sept 2022



Concaving road surface from heavy vehicles – Oct 2022



Fly tipping – October 2022



Backfilled areas where ground has sunken and water retention on site – October 2022



June 2020 – clean up begins ready for NHS test centre

Surface mud on roundabout



Surface mud on thrid exit of roundabout



